

TO 1F-15C-3-2






Figure 3-55. Main Structure (Sheet 1 of 7)



Accident Aircraft Fatigued Longeron



**Location of
Cracks Found
During
Inspections**

**New
Inspection
Focus**

Figure 3-55. Main Structure (Sheet 1 of 7)

New Inspection Area Two Seat F-15 (Typical Left & Right Side)

